Walkability Audit

Hedgestown NS

A Walkability Audit is an investigation into how walkable a route is.

The Green-Schools Committee investigated the path in both directions in front of their school to see what the walking infrastructure exists on the route.

Porch area to gather and acts as shelter from weather.

Large area for students and parents to gather and chat.

Bike shelter with cover at front of school.

Water pump by the school vegetable plots is a point of interest.

Wide path from school , out onto road alongside school.

Cutting back of the hedging helps visibility along the route.

Walkability Audit

Hedgestown NS

A Walkability Audit is an investigation into how walkable a route is.

The Green-Schools Committee investigated the path in both directions in front of their school to see what the walking infrastructure exists on the route.

- Very faded "Children Crossing" sign on roundabout, near school entrance

- School Zone flashing sign on approach to school .

Moss along path makes path narrow.

Traffic travels very fast on the road outside the school.

Faded "Children Crossing" sign , going. eastwards towards school

Speed limit reduces to 60kmh infront of school .